

BellSouth Corporation
Suite 900
1133-21st Street, N.W.
Washington, D.C. 20036-3351

maryhenze@bellsouth.com

October 23, 2002

Mary L. Henze
Executive Director
Federal Regulatory Affairs

202 463 4109
Fax 202 463 4631

RECEIVED

OCT 22 2002

FEDERAL COMMUNICATIONS COMMISSION
OFFICE OF THE SECRETARY


Ms. Marlene H. Dortch
Secretary
Federal Communications Commission
445 Twelfth Street, S.W.
Washington, DC 20554

Re: Notices of Network Change Under Rule 51.329(a) CC Docket No. 96-98

Dear Ms. Dortch:

BellSouth Telecommunications, Inc. ("BellSouth") hereby submits the attached original and two copies of its Notices of Network Change Under Rule 51.329(a) in accordance with the requirements set forth in the Commission's Second Report and Order and Memorandum Opinion and Order released August 8, 1996, in CC Docket No. 96-98. A description of the network change is provided below:

Number	Type of Change Planned	Location of Change
91083378	Replacing Copper with Fiber	Hover, AL
91083380	Replacing Copper with Fiber	West Palm Beach, FL
91083381	Replacing Copper with Fiber	West Palm Beach, FL
91083382	Replacing Copper with Fiber	West Palm Beach, FL
91083383	Replacing Copper with Fiber	Riviera Beach, FL


Mary L. Henze
Executive Director - Federal Regulatory

Attachments

cc: Michelle Carey (with diskette) Carmell Weathers (with diskette)

Notice of Network Change - Hoover, AL Valley Wire Center **BRHMALU0158**
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier
BellSouth Telecommunications, Inc
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: 2nd Quarter **2003**

Location of Changes: Hoover, Al Valley Wire Center, Lorna Rd 8 Lorna Ln

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems due to copper cable damaged by gasoline

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC). e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service. but then utilizes the POTS-grade loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact: <u>Technical questions</u>	Dennis Johnson
relating to this change	3196 Hwy 280 S Rm 104N
should be directed to:	Birmingham, AL
	(205) 970-5429

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: **557-2647** (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: **1-800-786-7619**
Fax: **1-205-321-2191**

Notice of Network Change – Hoover, AL Valley Wire Center **HOVRALBUH01**
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: 2nd Quarter 2003

Location of Changes: Hoover, AL Valley Wire Center, Intersection of Lorna Rd, Rocky Ridge Rd, & Patton Chapel Rd

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems due to copper cable damaged by gasoline.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact: <u>Technical questions</u>	Dennis Johnson
relating to this change	3196 Hwy 280 S Rm 104N
should be directed to:	Birmingham, AL
	(205) 970-5429

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change • West Palm Beach, FL
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier
BellSouth Telecommunications, Inc
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: complete in April 2003

Location of Changes: Lake Colony (Palm Bay Circle), West Palm Beach, FL

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems due to copper cable failure.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact: <u>Technical questions</u>	M L Johns
relating to this change	2021 S Military Tr.
should be directed to:	West Palm Beach, FL 33415
	561 439-9186

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
780-2171 (FL, GA, NC, SC)
(If you are calling from a mandatory 10-digit calling area,
include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Notice of Network Change - West Palm Beach, FL
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier
BellSouth Telecommunications, Inc
675 West Peachtree Street **NE**
Atlanta, Georgia 30375

Date Changes are to Occur: complete in April 2003

Location of Changes: North and South side of Dr. Martin Luther King Jr. Blvd

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems due to copper cable failure.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit **to** one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the **POTS-grade** loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact: <u>Technical questions</u> relating to this change should be directed to:	M L Johns 2021 S Military Tr. West Palm Beach, FL 33415 561 439-9186
---	--

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (**LISC**). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region:	557-2647 (AL, KY, LA, MS, TN) or 780-2171 (FL, GA, NC, SC) (If you are calling from a mandatory 10-digit calling area, include your local area code.)
--------------------------	--

Outside BellSouth region:	1-800-786-7619
Fax:	1-205-321-2191

Notice of Network Change - West Palm Beach, FL
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Complete by May 2003

Location of Changes: Southern portion of the Steeplechase subdivision

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems due to Department of Transportation road improvements.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact:	<u>Technical Questions</u>	M L Johns
	relating to this change	2021 S Military Tr.
	should be directed to:	West Palm Beach, FL 33415
		561 439-9186

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region:	557-2647 (AL, KY, LA, MS, TN) or
	780-2171 (FL, GA, NC, SC)
	(If you are calling from a mandatory 10-digit calling area,
	include your local area code.)

Outside BellSouth region:	1-800-786-7619
Fax:	1-205-321-2191

Notice of Network Change - Riviera Beach, FL
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Date Changes are to Occur: Complete by June 2003

Location of Changes: Military Trail 1 mile north of 45th Street to Blue Heron Blvd W

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact:	<u>Technical questions</u> relating to this change should be directed to:	M L Johns 2021 S Military Tr. West Palm Beach, FL 33415 561 439-9186
-----------------	---	---

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 557-2647 (AL, KY, LA, MS, TN) or
 780-2171 (FL, GA, NC, SC)
 (If **you** are calling from a mandatory IO-digit calling area.
 include your local area code.)

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191